

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: FUEL SPILL

DATE OCCURRED 08-09-93

DATE REPORTED _____

TIME OCCURRED 1045

TIME REPORTED _____

LOCATION(S) OF OCCURRENCE:

WEST OF GALVINS BLDG 7149 ON RAMP

REPORTED BY:

PHONE NO(S):

GALVINS

SUMMARY:

GALVINS REPORTED FUEL SPILL FROM JET (N230A) AT ABOVE LOCATION. OFFICER DICKIE RESPONDED IN FD 2. APPROXIMATELY 10-15 GALS OF JET FUEL WERE SPILLED. GALVIN LINEMAN SAID THERE WAS A DEFECT IN AIRCRAFT FUEL COUPLING. GALVIN EMPLOYEES HAD PUT A FUEL ABSORBANT SUBSTANCE ON THE SPILL. JET WAS ALLOWED TO PULL AWAY. OFFICER DICKIE HELPED GALVIN EMPLOYEES SWEEP UP MATERIAL. OFFICER DICKIE THE PUT CEJAR ON SPILL AND WASHED IT DOWN.

OFFICERS:

ACTION:

LEB	CLD	GO	JW
JED	JEC	LGR	FILED
TKL	GCS	BY	
PCM	JRV		